

PRESTBURY UNITED REFORMED CHURCH - FIRE RISK ASSESSMENT (Updated 3 Oct 2022)

Risk No	Risk	Likelihood	Impact	Mitigations
1	Electrical fault (infrastructure) Fuseboxes, Wiring, Wall Heaters, Lights	UNLIKELY	MINOR to SEVERE	Single-storey building 2 clearly marked fire exits at opposite ends of the building 6 fire extinguishers & fire blanket - checked annually (last check Nov 2021) Electrical Safety Check every 5 years - Last done July 2022
2	Electrical fault (appliances) Kitchen appliances - Cooker, Microwave, Water Heater, Urn, Kettles, Toaster Fan Heaters, Vacuum cleaners, Organ, Sound system	POSSIBLE	MINOR to SEVERE	Single-storey building 2 clearly marked fire exits at opposite ends of the building 6 fire extinguishers & fire blanket - checked annually(last check Nov 2021) Portable Appliance Testing (PAT) every 2 years - Last check July 2022
3	Act of God - lightning etc?	REMOTE	MINOR to SEVERE	Single-storey building 2 clearly marked fire exits at opposite ends of the building 6 fire extinguishers & fire blanket - checked annually (last check Nov 2021)
4	Human Carelessness Cigarettes, matches, candles, misuse of appliances	POSSIBLE	MINOR to SEVERE	Single-storey building 2 clearly marked fire exits at opposite ends of the building 6 fire extinguishers & fire blanket - checked annually (last check Nov 2021) NO SMOKING signs Discourage use of candles. use sand tray when possible. Have snuffer to hand. Whoever lights candle is responsible for extinguishing it Clear instructions with appliances
5	Fire in adjacent premises spreads to Church	REMOTE	MINOR to SEVERE	Single-storey building 2 clearly marked fire exits at opposite ends of the building 6 fire extinguishers & fire blanket - checked annually No immediately adjoining buildings - albeit a thatched cottage next door!
6	Vandalism / Arson attack	POSSIBLE	MINOR to SEVERE	Single-storey building 2 clearly marked fire exits at opposite ends of the building 6 fire extinguishers & fire blanket - checked annually (last check Nov 2021)
7	Act of Terrorism	REMOTE	MINOR to SEVERE	Single-storey building 2 clearly marked fire exits at opposite ends of the building 6 fire extinguishers & fire blanket - checked annually (last check Nov 2021)